LUNN

The state of the s	Inspection Type / / Inventory No. 0324/8 Inspection Frequency status Authorization
	Violation Code Authorized to Inject
	Company/Operator KWB Oil Properties Management dua. Business Address 15 East 5th St. # 3300 Tulsa, Ok 74/03
	Individual Contacted Title
	Lease Name' & Well No. #29
	Legal Description (b) (9) Well Information: SWD/ER, ACTIVE/TA/P&A
Ì	
	Authorized Injection: Pressure Rate
	Long String Casing Size Tubing Size
	Report of Conditions as of this Date: Lease: Active/Inactive Well hooked up for injection: Yes/No Injecting at time of inspection: Yes/No Required fittings on tubing and casing/tubing annulus: Yes/No/Not Applicable Injection Pressure ### ; How Determined ####################################
	Had ~ 40 gring luse goinge. Annulus Rad a moderate pull to gero when opened Removed bullglug; faully valve. Weather Conditions and Observations mostly cloudy, south winds
	35 mm 5300 MD Kodak, ASA 100, time, 1535
	Mantal Ma
W.	aran 1465 118-118-441 ang ar rayan 20 an 146 2m